### New Hampshire Department of Transportation

## **Bridge Inspection Report**

Hancock 125/049 NBI Structure Number: 011201250004900

Date of Inspection: 08/10/2022 **TANNERY HILL ROAD** 

**Date Report Sent:** 12/28/2022

Owner: Municipality

Bridge Inspection Group: D-Team Bridge Maintenance Crew: OTHER

**Existing Bridge Section** Bureau of Bridge Design

**FERGUSON BROOK** 

**Recommended Postings:** 

Weight: No Posting Required ✓ Weight Sign OK

Width: Not Required ✓ Width Sign OK

Primary Height Sign Recommendation: None ✓ Height Sign OK Over: 99.99 Clearances:

Optional Centerline Height Sign Rec: None (Feet) Under: 0.00

Route: 99.99

Condition: **Structure Type and Materials:** 

Red List Status: Not on the Redlist Number of Main Spans: Deck: 8 Very Good Number of Approach Spans:

Superstructure: 8 Very Good Main Span Material and Design Type

Substructure: 8 Very Good Concrete/Slab Culvert: N N/A (NBI) Sufficiency Rating: 95 %

NH Bridge Type: CRF-P (Conc Rigid Frame-Precast Bridge Rail: Meets Standards

Rail Transition: Meets Standards Deck Type: Concrete Precast Panel

Bridge Approach Rail: Meets Standards Wearing Surface: Bituminous

Membrane: Preformed Fabric Approach Rail Ends: Substandard

Deck Protection: Epoxy Coated Reinforcing

Curb Reveal: 7 in

Plan Location: M1-4-4-3 **Bridge Dimensions:** 

Total Bridge Length: 31.0ft Length Maximum Span: 28.0 ft Right Curb/Sidewalk Width: 0.0 ft Left Curb/Sidewalk Width: 0.0 ftTotal Bridge Width: 27.0ft

Width Curb to Curb: 24.0 ft Median: No median Approach Roadway Width: 22.0 ft

(W/Shoulders) Bridge Skew: 0.00° Year Built/Rebuilt: 2002

### Existing Bridge Section Bureau of Bridge Design

## Hancock 125/049

## **Bridge Inspection Report**

NBI Structure Number: 011201250004900

## **Bridge Service:**

Type of Service on Bridge: Highway

Type of Service Under: Waterway

Lanes on Bridge: 2 Lanes Under: 0

AADT: 223 Percent Trucks: 4% Year of AADT: 2022 Future AADT: 330 Year of Future AADT: 2042

Federal or State Definition Bridge: Fed-Definition Bridge

National Highway System: Bridge does not carry NHS

Roadway Functional Class: Rural, Local

New Hampshire Bridge Tier: 5

Eligibility for the National Register of Historic Places: Not eligible for NRHP

Traffic Direction: 2-way traffic

## National Bridge Inventory (NBI) Appraisal Ratings:

Deck Geometry: 5 Above Tolerable
Underclearances: N Not applicable (NBI)
Approach Alignment: 6 Equal Min Criteria
Structural Evaluation: 8 Equal Desirable Crit

Channel/Channel Protection: 8 Protected

Waterway Adequacy: 8 Equal Desirable

Bridge Scour Critical Status: 8 Stable Above Footing

Riprap Condition: Good Condition

Debris Present: No Debris Present

**Channel Notes:** 

## **Bridge Inspection Report**

NBI Structure Number: 011201250004900

Hancock 125/049

#### **Element Details**

No.	Description	Material Notes and Condition Notes:
38	Reinforced Concrete Slab	** Con-Span ** (5 SECTIONS)
		28' CS X 8' RISE.
		NEW 2002. MEMBRANE, 12"-15" GRAVEL COVER, 3" PAVEMENT.
		CURBS- FINE CRACKS. UNDERSIDE OF SLAB- MINOR SCRAPES AT LIFTING PORTS
		DURING INSTALLATION.
510	Wearing Surfaces	ASPHALT- NO DAMAGE.
		WWW.GO.W.G.W.D.ED
215	Reinforced Concrete Abutment	WINGS INCLUDED.
		ABUTMENTS- FINE CRACKS ON HEADWALLS. HEADWALL RUST STAINED IN AREAS FROM
		WEATHERING STEEL BRIDGE POST.
333	Other Bridge Railing	GLUED LAMINATED TIMBER 10.5" X 6.75" ON W6 X 20 STEEL POST.
		TIMBER RAIL- LIGHT CRACKS.

#### **Element States**

No.	Description	Quantity	Units	State 1	State 2	State 3	State 4
38	Reinforced Concrete Slab	837	sq.ft	100%	0%	0%	0%
└ 510	Wearing Surfaces			100%	0%	0%	0%
215	Reinforced Concrete Abutment	145	ft	100%	0%	0%	0%
333	Other Bridge Railing	144	ft	100%	0%	0%	0%

#### **Bridge Notes:**

NEW BRIDGE 2002. \*\* Con-Span \*\* (5 SECTIONS) 28' CS X 8' RISE. MEMBRANE, 12"-15" GRAVEL COVER, 3" PAVEMENT. ADDED DECK ELEMENT #52, 7/10/2015.

**Inspection Notes:** 08/10/2022 BTB inspection comments-

DECK / SUPERSTRUCTURE: ASPHALT- NO DAMAGE. CURBS- FINE CRACKS. UNDERSIDE OF SLAB- MINOR SCRAPES AT LIFTING PORTS DURING INSTALLATION. TIMBER BRIDGE RAIL- LIGHT CRACKS.

SUBSTRUCTURE: ABUTMENTS- FINE CRACKS ON HEADWALLS. HEADWALL RUST STAINED IN AREAS FROM WEATHERING STEEL BRIDGE POST.

PICTURES: 277-54. WEST APPROACH. 55. SOUTH ELEVATION.

Previous Inspection Notes: 08/10/2020

NJL inspection comments-

DECK / SUPERSTRUCTURE: ASPHALT- NO DAMAGE. CURBS- FINE CRACKS. UNDERSIDE OF SLAB- MINOR SCRAPES AT LIFTING PORTS DURING INSTALLATION. TIMBER BRIDGE RAIL- LIGHT CRACKS.

SUBSTRUCTURE: ABUTMENTS- FINE CRACKS ON HEADWALLS. HEADWALL RUST STAINED IN AREAS FROM WEATHERING STEEL BRIDGE POST.

### **Approach and Roadway Notes:**

APPROACH ASPHALT- NO DAMAGE. APPROACH RAIL- MINOR SCRAPES ON TIMBER.

# **Bridge Inspection Report**

NBI Structure Number: 011201250004900

Hancock 125/049

### **Inspection History**

Inspection	Inspector	Inspection Type(s) Performed			Major Element Ratings				Red	Posting		
Date	Initials	NBI	Elem	FCM	U/W	Deck	Super	Sub	Culvert	list	Posting	
08/10/2022	BTB	✓	<b>✓</b>			8	8	8	N		No Posting Req'd	
08/10/2020	NJL	✓	<b>✓</b>			8	8	8	N		No Posting Req'd	
08/06/2018	NJL	✓	<b>✓</b>			8	8	8	N		No Posting Req'd	
08/05/2016	KLM	✓	<b>✓</b>			8	8	8	N		No Posting Req'd	
07/10/2015	NJL	✓	✓			8	8	8	N		No Posting Req'd	
08/15/2013	NJL	✓	<b>✓</b>			8	8	8	N		No Posting Req'd	
08/03/2011	MHC	✓	<b>✓</b>			8	8	8	N		No Posting Req'd	
08/10/2009	KLM	✓	<b>✓</b>			8	8	8	N		No Posting Req'd	
03/01/2007	FNM	<b>✓</b>	<b>✓</b>			8	8	8	N		No Posting Req'd	
11/01/2006	FNM	<b>✓</b>	<b>✓</b>			8	8	8	N		No Posting Req'd	
09/22/2004	JEL	<b>✓</b>	<b>✓</b>			9	9	9	N		No Posting Req'd	
10/14/2002	FNM	<b>✓</b>	<b>✓</b>			9	9	9	N		No Posting Reg'd	

Inspection Frequency (mo.)								
NBI	Elem	FCM	U/W					
24	24	N/A	N/A					